Designations in the drawings for the article of P. N. Rybkin.

A is the antenna.
P is the coherer or radio conductor.
c is the shock or shock.
D - extension coil.
U - autotransformer (transform. Uden).
Kl is the transmitting key.
K is the capacitor.
L - Leiden bank.
h - grounding.
And - induction apparatus (when it indicates the maximum length of its spark).
and - the spark gap (when it indicates its length).
n - breaker.
k is the capacitor to the breaker.
B - battery of elements.
Sat - without induction resistance.
P - relay.
T is the telephone.
M is the Morse apparatus.